

Annex 5 – Photos



Photo 1500-1. View to the former bilge water separator close to the bore hole 1529; Visible thick layer of oil



Photo 1500-2. View to the same bilge water separator; in the left farther corner is visible end of pipe, where to can flow also the free phase of oil



Photo 1500-3. View to the trench for collecting of free phase of oil; on the water is visible thick oil layer and on the slopes of trench is contaminated soil



Photo 1500-4. View to the same trench from north side; on the water is visible oil film



Photo 1500-5. View to cleaning process of the former bilge water separator in year 2006; (Photo from EcoPro report)